## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/28/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING  01		(X3) DATE SURVEY COMPLETED		
		155516	B. WING			06/21/2012		
NAME OF PROVIDER OR SUPPLIER  PARKVIEW MEMORIAL HOSPITAL-CCC				220	ET ADDRESS, CITY, STATE, ZIP CODE 10 RANDALLIA DR RT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREF TAG			OULD BE	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS		К	000				
	A Life Safety Code and Environmental Preoccupancy Survey for the relocation of the CCC unit from the fifth floor East and West wings to the 5th South Extended Unit and the addition of 3 beds, two in room 1524 and one in room 1525 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).  Survey Date: 06/21/12  Facility Number: 001203 Provider Number: 155516 AIM Number: N/A  Surveyor: Amy Kelley, Life Safety Code Specialist  At this Life Safety Code and Environmental Preoccupancy survey, Parkview Memorial Hospital-CCC was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety From Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) Chapter 19, Existing Health Care Occupancies, and with 410 IAC 16.2-3.1-19, Environment and Physical Standards of the Indiana Health Facilities Rules for Comprehensive care facilities for the relocation and addition of three beds in the aforementioned rooms.  The fully sprinklered Parkview Memorial Hospital - CCC is now located on the fifth floor, 5th South Extended Unit of a nine story hospital of Type I (332) construction with a basement. The facility has a fire alarm system with smoke detection at							
ABORATORY	I DIRECTOR'S OR PROVIDER	X/SUPPLIER REPRESENTATIVE'S SIGNATURE	<u> </u>		TITLE		(X6) DATE	

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 06/28/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  01			(X3) DATE SURVEY COMPLETED			
		155516	B. WIN	G		06/2	21/2012		
NAME OF PROVIDER OR SUPPLIER  PARKVIEW MEMORIAL HOSPITAL-CCC				STREET ADDRESS, CITY, STATE, ZIP CODE  2200 RANDALLIA DR  FORT WAYNE, IN 46805					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG		PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	ION SHOULD BE COMPLET THE APPROPRIATE DATE			
K 000	the corridor smoke be the corridor and in all facility has a capacity 27 at the time of this Quality Review by Ro	arrier doors, areas open to the resident rooms. The of 31 and had a census of	K	000					